




Photograph 16
P01. Catalytic Trailblazer Genesis 2000.



Photograph 17
P01. Cracked baffle in the Catalytic Trailblazer Genesis 2000.



Photograph 18
P01. Degraded catalyst in the Catalytic Trailblazer Genesis 2000.




Photograph 19
P02. Non-catalytic Lopi Answer Series.



Photograph 20

P02. Degraded support for the front secondary air tube in the non-catalytic Lopi Answer Series.



Photograph 21


P02. Creosote deposits on the secondary air tube in the non-catalytic Lopi Answer Series.



Photograph 22
P03. Non-catalytic Lopi 380-96.




Photograph 23
P04. Catalytic Flush Bay-96 (now Freedom).



Photograph 24
P04. Warped and flaking secondary air tube in the Catalytic Flush Bay-96.



Photograph 25
P05. Catalytic Lopi Flex-95.



Photograph 26
P05. Disturbed catalyst interam seal in the Catalytic Flex-95.




Photograph 27
P06. Non-catalytic Pacific Energy Super 27.



Photograph 28
P06. Sagging baffle in the non-catalytic Pacific Energy Super 27



Photograph 29
P07. Non-catalytic Lopi 520-96.



Photograph 30
P07. Flaking secondary air tube in the non-catalytic Lopi 520-96.



Photograph 31
P08. Catalytic Vermont Castings Defiant Encore.